

# LH series weighing batching controller

## Instruction manual


Thanks a lot for selecting our products.

Before operating this instrument, please carefully read this manual and fully understand contents. If any problems, please contact our sales distributor whom you buy from. This manual is subject to change without prior notice.

### Application

The instrument provides isolated auxiliary power (regularly 5V/80mA) which allows 1-4 kind loadcells connection directly. Up to 6 control outputs are available for group ingredients weighing or fast/slow weighing. Data/Peak value holding function for choice. RS485 communication interface provides remote link with PC/PLC. Besides you can Start/Pause/Accumulate/Clear/Tare weight/average/clear zero, etc. for the displaying weight with external control terminal.

### Code illustration




1. Measuring values / Parameter code display
2. Parameter value / Preset value
3. Control output indicate lamps: On: active, Off: inactive  
Out1, Alarm1, Out2, Alarm2, BT/SV2:Alarm3
4. Parameter select / Confirm key
5. Shift key / Tare weight Clear key
6. UP key
7. DOWN key

## Specification

<b>Power</b>	90~260 VAC/DC or 15~30VAC/DC
<b>Power consumption</b>	$\leq 5\text{VA}$
<b>Accuracy</b>	0,1%FS $\pm 2$ digit (24bit A/D conversion)
<b>Sampling speed</b>	16~128 times/second
<b>Relay</b>	250VAC/3A or 30VDC 3A $\cos\phi = 1$
<b>Input</b>	mV(ladcell)
<b>Analog output</b>	4~20mA output configurable by software
<b>Auxillary power</b>	5VDC 80mA
<b>Communication</b>	RS485 MODBUS RTU protocol
<b>Mounting dimensions</b>	$91^{+0.5} \times 45^{+0.5}$

## Code illustration



## **Parameters setting**

### **1. Parameter setting:** In displaying estate,

- a. Press and hold SET key >3s, enter/quit parameters setting menu,
- b. Press <</RET key, LED flashes
- c. Press UP/DOWN key to modify
- d. Press SET key to confirm
- e. Press SET key again to read the following parameters one by one.

### **2. Adjustment:**


- a. Well connected wires and sensor, turn power on.
- b. Parameter SEL settings. Press UP and DOWN key >3s to enter the menu set the data in hundredth bit to 0. Press SET key to confirm.
- c. Set USP = Standard weight (suggest more than 20% load cell scale) set PVF=0000
- d. Without any weight on the instrument press DOWN key >5s until OK flashes. That's to set the zero point and displays 0.0.
- e. Add the weight equal to setted USP, press UP key >5s until OK flashes. That's to set the high value and it displays the added weight.
- f. Should big error happens, just repeat the above operation.
- g. After finish the above operation, press <</Rst key >2s, to be clear tare weight.
- h. Parameter SEL setting press UP nad DOWN key >3s to enter the menu set the data in hundredth bit to 1. Press SET key to confirm.

### **3. Clear tare weight:**

In display estate press <</Rst key >2s to clear, then it displays 0.

- 4. The instrument will return to the measuring estate without any operation for 25 seconds.
- 5. When accumulated/average function is needed. The accumulate value will be in the low LED. Press external terminal RST to reset, SUM to add up the value will be added when each operation to SUM.
- 6. Decimal point setting for parameter AL1, AL2, AL3, HY1, HY2, PVF, USP, tRL, tRH press <</Rst key, LED flashes, then one hand to hold SET key, and the other hand to press UP key to shift the decimal point. Press SET key again to confirm and save.

## Operation process



## Parameter settings

SET key >3s

- ↓SET
- |          |                                  |
|----------|----------------------------------|
| AL 1     | Alarm 1 settings, range:0~999999 |
| 90.00000 |                                  |
- ↓SET
- |      |  |
|------|--|
| AL 1 | Alarm 1 mode settings L:low output, H:High ouput |
| H    |  |
- ↓SET
- |          |                                  |
|----------|----------------------------------|
| AL2      | Alarm 2 settings, range:0~999999 |
| 30.00000 |                                  |
- ↓SET
- |     |  |
|-----|--|
| AL2 | Alarm 2 mode settings L:low output, H:High ouput |
| H   |  |
- ↓SET
- |           |   |
|-----------|---|
| HY 1      | Alarm hysteresis value settings (for AL1, AL2) range:0~999999 |
| 100.00000 |   |
- ↓SET
- |          |  |
|----------|--|
| AL 3     | Alarm 3 setting. (not available if no AL3) |
| 40.00000 |  |
- ↓SET
- |      |  |
|------|--|
| AL 3 | Alarm 3 mode settings L:low output, H:High ouput |
| H    |  |
- ↓SET
- |          |  |
|----------|--|
| HY2      | Alarm hysteresis value settings (for AL3) range:0~999999 |
| 0.000000 |  |
- ↓SET
- |         |  |
|---------|--|
| PVF     | Material loss compensation value setting.<br>(PV(displaj value)=actual value +PVF) |
| 206.000 |  |
- ↓SET
- |         |   |
|---------|---|
| USP     | Reference weighing for calibration/Loadcell scale: range:0~999999 |
| 206.000 |   |
- ↓SET
- |         |  |
|---------|--|
| dP      | Decimal point setting for PV value: 000000, 000.000, 0.00000,... |
| 000.000 |  |
- ↓SET
- |         |  |
|---------|--|
| E-L     | Response for 4mA output low value setting range:0~999999 |
| 0.00000 |  |
- ↓SET

**E-H**  
100.000

Response for 20mA output high value setting range:0~999999

↓SET

**SFE**  
005

Digital filter constant.

- 0: direct display
- 1: mean value of 2 sampling display
- 2: mean value of 4 sampling display

↓SET

**Unit**  
003

Units selection (inactive)

↓SET

**Add**  
001

Communication address: 000~250

↓SET

**LCK**  
000

LCK=010 is for read only

LCK=000 means the parameter can be modified.  
Password selection range 0~200.

## Connection

Refer the label on the meter

## Adjusting for large-tonnage scale loadcell:

- A: Set USP=the total weight of all input loadcells (eg. each loadcells is 1000Kg, 3 loadcells in total, the total weight is 3000Kg. Then set USP=3000)  
Set PVF=0.000
- B: Record the display value (PV1) when no weight on the loadcells (eg.100.5Kg).
- C: Add the standard weight (the weight should be larger than 20% of the total loadcell weight, eg. 500Kg). Recorder the displaying value (PV2) (eg. 630Kg).
- D: Calculation : The actual weight added (eg.500Kg)/(PV2-PV1)  
eg.  $500/(630-100.5) = 0.9442$
- E: Calculation: USP\*(The actual weight added/(PV2-PV1)).  
eg.  $USP*(500/529.5)=2832.86$  then set USP=2832.86 again.
- F: The adjustment is finished.